

LOCATION: ST-2-466

HYDRAULIC CONDITIONS: Apparent Confined

PERTINENT OBSERVATIONS: Water was first detected while drilling between 440'-445'. No water detected while making a connection at 434'. When soap was turned off while refilling water truck, a large head of water accumulated in borehole at 454'. Borehole was advanced to 484' and was left to recover overnight. Static water level the next morning was 397.65', measured from the top of surface casing.